

+

CPU Heart BEAT

+

CPU Pending DOOM

+

CPU AC Power OFF

+

CPU AC Power ON

+

CPU Booting WAIT

+

WDPC ARMED

+

WDPC ALIVE

+

WDPC BYPASS

+

:

+

WDPC PWR ON

OCRG WDPC

Oregon Coast Repeater Group

WatchDog Power Cycler

120 VAC Input
12 AMP Max

WDPC Controlled
120 VAC Output
12 AMP Max

ON
Bypass
OFF

HeartBeat

Pinout :
2 - Out (optional) (TTL)
3 - Input (TTL, RS-232)
5 - Ground

Serial No. 10001
Rev. A01